

Message

---

**From:** Roberts, Lou [Roberts.Lou@epa.gov]  
**Sent:** 8/10/2017 9:54:59 PM  
**To:** Moore, Gary [Moore.Gary@epa.gov]  
**Subject:** FW: Frank J. Doyle Site

FYI

---

**From:** Roberts, Lou  
**Sent:** Friday, March 13, 2015 11:40 AM  
**To:** Moore, Gary <moore.gary@epa.gov>  
**Cc:** Sales, James <sales.james@epa.gov>  
**Subject:** RE: Frank J. Doyle Site

THANK YOU GARY

Lou Roberts (6EN-HM)  
US EPA Region 6  
1445 Ross Avenue, Suite 1200  
Dallas, TX 75202-2733  
(214) 665-7579  
Fax (214) 665-7446

"This email may contain material that is confidential, privileged and/or attorney work product and is for the sole use of the intended recipient. Any review, reliance or distribution by others or forwarding without express permission is strictly prohibited. If you are not the intended recipient, please contact the sender and delete all copies."

---

**From:** Moore, Gary  
**Sent:** Friday, March 13, 2015 11:38 AM  
**To:** Roberts, Lou  
**Cc:** Sales, James  
**Subject:** RE: Frank J. Doyle Site

Lou/Jim:

I talked with TCEQ (Elenor W.) and she indicated this site is in their corrective action group and she is the project manager. She indicated that they are having difficulty getting anyone to do anything. EPA apparently did a removal assessment in 1995 but the facility was still active. I am not sure if we did anything else after that (apparently no cleanup). I am not sure who you are going to be talking to next Wednesday but it would be a good idea to have TCEQ on the phone. I will send you her information when I get it.

Thanks

Gary Moore  
Federal On-Scene Coordinator  
U.S. EPA Region 6  
214-789-1627 cell  
214-665-6609 office

[moore.gary@epa.gov](mailto:moore.gary@epa.gov)

---

**From:** Moore, Gary  
**Sent:** Thursday, March 12, 2015 12:04 PM  
**To:** Roberts, Lou  
**Cc:** Chris Petersen  
**Subject:** Frank J. Doyle Site

Lou:

This is what I found out.

Site Name: Frank J. Doyle Site  
SSID: 061D  
EPA ID: TXD980865109  
Location: Cottonwood Drive, Leonard, Fannin County, Texas  
Employee: Robert Sullivan

My suggestion is to call Chris Petersen and see if he can assist in locating the file on this site. I am not sure what may have been done. My assumption would be that we may have done a removal assessment but we will not know until the file could be located. This site came up once before but I don't know if anyone was ever assigned. Robert Sullivan is now an RPM. He was an OSC at the time this would have been looked at.

Thanks

Gary Moore  
Federal On-Scene Coordinator  
U.S. EPA Region 6  
214-789-1627 cell  
214-665-6609 office  
[moore.gary@epa.gov](mailto:moore.gary@epa.gov)